



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4030-041
Job Sheet 186848



Part No: D4030-041

Job Qty: 1 ea

Part Name: Long Basket Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/22/18

Job Tracking No:

Due Date: 12/14/18

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV D SHEETS 1,3,4 IPP Rev:A new issue DD 10.03.23 verified by:EC IPP Rev:B as per dwg revB DD 10.04.20 verified by:EC IPP Rev:C as per dwg revC DD 10.08.18 verified by:EC IPP Rev D 12.03.27 per NCR12-1239 EC verified by:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	12/14/18	12/14/18	0.00	0.00	Start Up Stores/Pkg-1		BEB 18-12-29
100	Packaging	1 pcs	12/14/18	12/14/18	0.00	0.00	Packaging1-4		BEB 18-12-29
110	HandFinish	1 pcs	12/14/18	12/14/18	0.00	1.03	HandFinish4		BEB 18-12-29
120	QC	1 pcs	12/14/18	12/14/18	0.00	0.00	QC5		DAS 2018 68
130	Packaging	1 pcs	12/14/18	12/14/18	0.00	0.00	Packaging3-2		69 9-89
140	QC21-SA	1 Ea	12/14/18	12/14/18	0.00	0.00	QC21		DE 69 1 2018

DAS
70
9-89

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN3-14A/59	Bolt	4 Ea (4 ea)	90-Start up Operation	5130323
AN3-16A	Bolt	2 Ea (2 ea)	90-Start up Operation	5089276
AN310-4	Nut	3 Ea (3 ea)	90-Start up Operation	5121225
AN310C4	Nut	2 Ea (2 ea)	90-Start up Operation	5103854-1
AN4-12	Bolt	3 Ea (3 ea)	90-Start up Operation	2,5113819/1x5074 206.
AN5-17A	Bolt	4 Ea (4 ea)	90-Start up Operation	5112904
D2530	Handle Weldment	1 Ea (1 ea)	90-Start up Operation	5134576
D2535	Spring	2 Ea (2 ea)	90-Start up Operation	515452 5121 157.
D2537	Bushing	2 Ea (2 ea)	90-Start up Operation	5115452
D3917-3	Washer	6 Ea (6 ea)	90-Start up Operation	5124370
D3953-17	Gas Spring Spacer	2 Ea (2 ea)	90-Start up Operation	5117415
D3953-19	Gas Spring Bracket	1 Ea (1 ea)	90-Start up Operation	5120145
D3953-21	Gas Spring Bracket	1 Ea (1 ea)	90-Start up Operation	5112717
D3953-3	Gas Spring Stud, Lid	2 Ea (2 ea)	90-Start up Operation	5138740
D3953-7	Spring Spacer	2 Ea (2 ea)	90-Start up Operation	5115826
D3953-9	Gas Spring Washer	2 Ea (2 ea)	90-Start up Operation	5115399
D3969-3	Spring (Basket Lid)	1 Ea (1 ea)	90-Start up Operation	5131605
MS21042L3	Nut	6 Ea (6 ea)	90-Start up Operation	5094592
MS21042L5	Nut	4 Ea (4 ea)	90-Start up Operation	5134602 5053 951-4
MS24665-151	Cotter Pin	3 Ea (3 ea)	90-Start up Operation	5124686 5053 951-4
MS24665-300	Cotter Pin	2 Ea (2 ea)	90-Start up Operation	5104465
NAS1149C0432R	Washer	2 Ea (2 ea)	90-Start up Operation	5050052-1
NAS1149F0332P	Washer	8 Ea (8 ea)	90-Start up Operation	5109991-1x4/5183 206x4.

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____ Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Skid-tube ☐</td> <td style="width: 15%;">Cross tube ☐</td> <td style="width: 15%;">Water Jet ☐</td> <td style="width: 15%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
										QC / QA Coordinator Approval															
Root Cause		FAULT CATEGORY																							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐																				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐																				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐																				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐																				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐																				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐																				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐																				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐																				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐																				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐																				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____																							
Misidentified ☐	Past Due ☐																								

NAS1149F0432P	Washer	6 Ea (6 ea)	90-Start up Operation
NAS1149F0563P	Washer	4 Ea (4 ea)	90-Start up Operation
D3913-041	Long Basket Base Assembly, 350	1 Ea (1 ea)	110-HandFinish
D3914-041	Long Basket Lid Assembly (350)	1 Ea (1 ea)	110-HandFinish

5083558-1
5067901-2
5137170
5137143

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	AN3-14A	4	302	0
	AN3-16A	2	68	0
	AN310-4	3	195	0
	AN310C4	2	80	0
	AN4-12	3	149	0
	AN5-17A	4	71	0
	D2530	1	5	0
	D2535	2	47	0
	D2537	2	24	0
	D3917-3	6	97	0
	D3953-17	2	31	0
	D3953-19	1	24	0
	D3953-21	1	11	0
	D3953-3	2	20	0
	D3953-7	2	92	0
	D3953-9	2	26	0
	D3969-3	1	5	0
	MS21042L3	6	2,282	0
	MS21042L5	4	415	0
	MS24665-151	3	115	0
	MS24665-300	2	73	0
	NAS1149C0432R	2	1,826	0
	NAS1149F0332P	8	851	0
	NAS1149F0432P	6	668	0
	NAS1149F0563P	4	685	0
110-HandFinish	D3913-041	1	1	0
	D3914-041	1	3	0

M. H. 007250

Part Specifications

Specifications could not be found.

M. H. 007251

Plex 11/22/18 8:31 AM Dart.lajeunesse.marie

1270 Aberdeen Street
Hewksbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartero.com
www.darterospace.com

DART
AEROSPACE

Container No: S140875



Part: D4030-041

Job No: 186848

Serial No/Batch: S140875

Revision: D

Inspector:

Exp Date:

Instructions: Various STC's

Date: 12/29/18

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table border="0"> <tr> <td>Skid-tube ☐</td> <td>Cross tube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>				Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
	Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																	
	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																	
	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																	
Large Fab ☐	Composite ☐	Supplier ☐																			

Date :	Step #:	QTY Effective :	MRB (QSI042) Approval
--------	---------	-----------------	-----------------------

Description Work Order Deviation 	Disposition 	Completed By
		Lead hand / Supervisor Approval Verification
		QC / QA Coordinator Approval

Root Cause <table border="0"> <tr> <td>Environment ☐</td> <td>No Re-verification ☐</td> <td>Pressure/Forced ☐</td> </tr> <tr> <td>Design ☐</td> <td>Operator ☐</td> <td>Bending ☐</td> </tr> <tr> <td>Doc/Data ☐</td> <td>Offset/Setup ☐</td> <td>Centre Not Concentric ☐</td> </tr> <tr> <td>Equip/Tooling ☐</td> <td>Supplier ☐</td> <td>Cracks ☐</td> </tr> <tr> <td>Handling/Pre ☐</td> <td>Training ☐</td> <td>Crimp/Kink/Ripple/Wave ☐</td> </tr> <tr> <td>Material ☐</td> <td>Use for Testing ☐</td> <td>Cuffs ☐</td> </tr> <tr> <td>Internal Transport ☐</td> <td>Poor Information ☐</td> <td>Crushing ☐</td> </tr> <tr> <td>Tribal Knowledge ☐</td> <td>Rushing ☐</td> <td>Heat Treat ☐</td> </tr> <tr> <td>LOA ☐</td> <td>Product Improvement ☐</td> <td>Wave/Twist in Tube ☐</td> </tr> <tr> <td>Substation ☐</td> <td>Process Improvement ☐</td> <td>Marks/Chatter ☐</td> </tr> <tr> <td>Past Expiry Date ☐</td> <td>Manufacturing Process ☐</td> <td></td> </tr> <tr> <td>Misidentified ☐</td> <td>Past Due ☐</td> <td></td> </tr> </table>			Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Design ☐	Operator ☐	Bending ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Past Expiry Date ☐	Manufacturing Process ☐		Misidentified ☐	Past Due ☐		FAULT CATEGORY <table border="0"> <tr> <td>Temperature/Cure ☐</td> <td>Power Loss/Surge ☐</td> <td>Positioned Wrong ☐</td> </tr> <tr> <td>Set-up ☐</td> <td>Folio/Program ☐</td> <td>Outside Dimensions ☐</td> </tr> <tr> <td>BOM/Route ☐</td> <td>Grain ☐</td> <td>Over/Under tolerance ☐</td> </tr> <tr> <td>Broken/Damage/Defect ☐</td> <td>Weld ☐</td> <td>Part Incorrect ☐</td> </tr> <tr> <td>Inspection Incomplete/Unqualified ☐</td> <td>Wrong Stock Pulled ☐</td> <td>Part Lost/Missing ☐</td> </tr> <tr> <td>Contamination ☐</td> <td>Out of Sequence ☐</td> <td>Part Moved ☐</td> </tr> <tr> <td>Countersink ☐</td> <td>Off-set ☐</td> <td>Drawing ☐</td> </tr> <tr> <td>Cut Too Short ☐</td> <td>Mislabeled ☐</td> <td>Finish ☐</td> </tr> <tr> <td>Instructions Incomplete/Unclear ☐</td> <td>Fit/Function ☐</td> <td>Misread ☐</td> </tr> <tr> <td>Drill Holes ☐</td> <td>Misaligned/off center ☐</td> <td>Turning Sequence ☐</td> </tr> </table>			Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Countersink ☐	Off-set ☐	Drawing ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
Environment ☐	No Re-verification ☐	Pressure/Forced ☐																																																																					
Design ☐	Operator ☐	Bending ☐																																																																					
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐																																																																					
Equip/Tooling ☐	Supplier ☐	Cracks ☐																																																																					
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐																																																																					
Material ☐	Use for Testing ☐	Cuffs ☐																																																																					
Internal Transport ☐	Poor Information ☐	Crushing ☐																																																																					
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐																																																																					
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐																																																																					
Substation ☐	Process Improvement ☐	Marks/Chatter ☐																																																																					
Past Expiry Date ☐	Manufacturing Process ☐																																																																						
Misidentified ☐	Past Due ☐																																																																						
Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐																																																																					
Set-up ☐	Folio/Program ☐	Outside Dimensions ☐																																																																					
BOM/Route ☐	Grain ☐	Over/Under tolerance ☐																																																																					
Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐																																																																					
Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐																																																																					
Contamination ☐	Out of Sequence ☐	Part Moved ☐																																																																					
Countersink ☐	Off-set ☐	Drawing ☐																																																																					
Cut Too Short ☐	Mislabeled ☐	Finish ☐																																																																					
Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐																																																																					
Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐																																																																					
OTHER : ☐																																																																							